

IMPORTANT SAFETY INSTRUCTIONS

 **Warnings:**

- The CT500 must be connected to a grounded, metal, permanent wiring system; or an equipment grounding conductor must be run with the circuit conductors and connected to the CT500's grounding terminal or lead.
- The CT500 must be installed by a qualified electrician and in accordance with all local electrical codes and ordinances.
- Read all instructions before installing the CT500. Refer to the CT500 Installation Manual included in the CT500's shipping box.
- Adult supervision is required when using the CT500 near children.
- Do not operate a CT500 with a visibly damaged cable. Contact Coulomb Technologies immediately.
- Do not operate a CT500 if the enclosure or the charging cord is broken, cracked, open, or shows any other signs of damage. Contact Coulomb Technologies immediately.
- Do not put fingers into the charging cord.
- Do not install the CT500 near flammable, explosive, or combustible materials.
- Do not operate the CT500 in temperatures outside its operating range of -22°F to 122°F (-30°C to +50°C).
- The CT500 contains no user-serviceable parts. Do not attempt to repair or service the CT500 yourself. If the CT500 requires servicing, contact Coulomb Technologies.
- Ensure that the CT500's charging cord is positioned so it will not be stepped on, tripped over, or subjected to damage or stress.

SAVE THESE INSTRUCTIONS

See reverse for operating instructions.



1692 Dell Ave.
Campbell, CA 95008-6901 USA
US toll free: +1-877-370-3802
www.coulombtech.com
www.mychargepoint.net

CT500 ChargePoint® Charging Station Operating Instructions

After the CT500 has been successfully installed and is displaying a message indicating that the station is available, you are ready to charge your vehicle by following these simple instructions.

To start charging:

1. If the CT500 is equipped with a card reader, hold a valid ChargePass™ card over the station's label. The station will display a message indicating that the card has been authorized.
2. Remove the charging cord from its holster and plug it into the vehicle.

The top light FLASHES green to indicate that the vehicle is charging. If it doesn't flash, return the connector to its holster and try again.

When the vehicle is fully charged, the light stops flashing and illuminates SOLID green.



To stop charging:

1. Unplug the vehicle and return the charging cord to its holster.

NOTE: You can also press the CT500's STOP button to stop charging at anytime without removing the connector. However, to start charging again, you will need to return the connector to its holster momentarily, then plug it back into the vehicle.

When you unplug the vehicle, the light illuminates SOLID green for 30 seconds while the CT500 displays the elapsed time of the charging session (HH:MM:SS).

After 30 seconds, the light extinguishes and the CT500 displays its original message, indicating that the station is available for charging.



See reverse for important safety instructions.



1692 Dell Ave.
Campbell, CA 95008-6901 USA
US toll free: +1-877-370-3802
www.coulombtech.com
www.mychargepoint.net

Document Part Number: 75-001021-01 Revision: 1.0

©2010 Coulomb Technologies, Inc. All rights reserved. This material is protected by the copyright laws of the United States and other countries. It may not be modified, reproduced or distributed without the prior, express written consent of Coulomb Technologies, Inc. CHARGEPOINT is a U.S. registered trademark and service mark of Coulomb Technologies, Inc. All other products or services mentioned are the trademarks, service marks, registered trademarks or registered service marks of their respective owners. Coulomb Technologies has filed several patent applications.